

CONVERSION TABLE

INCH	MILLIMETR	GAUGE
1/64	0,39	1
5/64	1,98	5
3/32	2,38	6
7/64	2,78	7
1/8	3,18	8
9/64	3,57	9
5/32	3,97	10
3/16	4,76	12
13/64	5,16	13
1/4	6,35	16
9/32	7,14	18
3/8	9,52	24
13/32	10,32	26
1/2	12,70	32
5/8	15,87	40
3/4	19,05	48
7/8	22,22	56
1	25,40	64
1 1/8	28,57	72
1 1/4	31,75	80
1 3/8	34,92	88
1 1/2	38,10	96
2	50,80	128